

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	1212	(219/74).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/11/06 10:11
S2	1581	(219/137WM).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/11/06 10:21
S3	563	(252/372).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/11/06 10:22
S4	163622	("219").CLAS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/11/06 10:33
S5	129315	("252").CLAS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/11/06 10:33
S6	52444	("228").CLAS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/11/06 10:33
S7	338335	S4 or S5 or S6	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/11/06 10:33
S8	549	S7 and ((weld\$3 near10 (steel or iron) near50 (inert or shield\$3 or gas or mixture) near50 (oxygen or carbon or dioxide or argon or helium or Ar or He)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/11/06 10:34
S9	20	S7 and ((weld\$3 near10 (steel or iron) near20 (ductile or cast) near50 (inert or shield\$3 or gas or mixture) near50 (oxygen or carbon or dioxide or argon or helium or Ar or He)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/11/06 10:35

S10	163622	("219").CLAS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/11/06 11:46
S11	129315	("252").CLAS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/11/06 11:46
S12	52444	("228").CLAS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/11/06 11:46
S13	338335	S10 or S11 or S12	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/11/06 11:46
S14	10	S13 and ((weld\$3 near50 (steel and iron and (ductile or cast)) near50 (inert or shield\$3 or gas or mixture) (oxygen or carbon or dioxide or argon or helium or Ar or He)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/11/06 11:46
S15	37	S13 and ((weld\$3 near50 (steel and iron and (ductile or cast)) near50 (inert or shield\$3 or gas or mixture or argon or helium or Ar or He)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/11/06 11:47
S16	118	((weld\$3 near50 (steel and iron and (ductile or cast)) near50 (inert or shield\$3 or gas or mixture or argon or helium or Ar or He)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/11/06 11:56
S17	68	((weld\$3 near10 (steel and iron and (ductile or cast)) near20 (inert or shield\$3 or gas or mixture or argon or helium or Ar or He)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/11/06 11:57

S18	2	((weld\$3 near10 (steel and iron and (ductile or cast)) near20 (inert or shield\$3 or gas or mixture or argon or helium or Ar or He))).clm.	US_PGPUB; USPAT	OR	OFF	2008/11/06 12:07
-----	---	--	--------------------	----	-----	---------------------

11/6/08 12:10:02 PM

C:\Documents and Settings\kkerns\My Documents\EAST\Workspaces\10539773(219)
rceu.wsp